

## VANGUARD Hardware Advisory Notice Release 6.1.T03A

### Introduction

This notice describes a revision change on the Vanguard Quad FXS card created by a manufacturing change in the SLIC chip design. Platforms: Vanguard 6435, 6455 and 340.


### Vanguard Quad FXS SLIC Chip

A manufacturing change in the SLIC chip design required the Quad FXS card to be revised from A to revision B. If you have a revision B Quad FXS card a 6.1 software patch is required (6.1.T03A). The Quad FXS revision B cards are not being recognized by software older than 6.1.T03A.

<i>Quad FXS Card</i>	<i>Software Version</i>
Quad FXS Card - Revision A	All releases
Quad FXS Card - Revision B	6.1.T03A and higher

### Checking the Revision of the Quad FXS Card

The arrow in Figure 1 shows the location of the revision label, located on the back right side of the Quad FXS card.



**Figure 1. Revision Number Label**



T0260 A

**Software Patch**  
**6.1.T03A**

---

The default images and executable patch are available at:

**[http://www.vanguardms.com/support/software\\_and\\_tools/vanguard/special\\_releases/](http://www.vanguardms.com/support/software_and_tools/vanguard/special_releases/)**

---