

Vanguard Applications Ware Point Release 6.5P03A Advisory Notice

Introduction

This notice contains information on software improvements and changes made by the Vanguard Applications Ware Point Release 6.5P03A.

This notice supplements the *Vanguard Applications Ware Release 6.5.R000 SoftwareRelease Notice* (Part Number T0001-47).

Install Service Pak Executable File

Follow these steps to install the Point Release 6.5P03A patch executable file:

Step	Action
1	If you have not already done so, install Vanguard Software Builder from any Vanguard Release 6.5.R000 CD-ROM (Part Number 72608-36 A).
2	Download the V65P03A.ZIP file from Vanguard Managed Solutions, please save the file to a local drive on your computer.
3	Use WinZip® to extract the ZIP file. The V65P03A.ZIP file contains the V65P03A.EXE file and a copy of this advisory notice in PDF format.
4	Run or open the V65P03A.EXE executable file from your local drive.
5	The patch executable file prompts you with installation instructions. Insert the Vanguard 6.5.R000 CD-ROM into the CD-ROM drive and select its drive letter. Follow the installation instructions provided by the installer.



T0279 A

Build an Image

After you install the Point Release Patch executable file, you must build a custom release and load the custom image. This table provides general instructions for these procedures:

■Note

For detailed instructions on building a software image and using the Vanguard Software Loader, see the *Vanguard Software Builder Manual* (Part Number T0030) and the *Vanguard Software Loader Manual* (Part Number T0057).

Step	Action
1	Using Vanguard Software Builder, build a custom Release 65P03A Point Release image by selecting the appropriate Point Release (V65P03A for example) from the Release drop-down menu. Select features or options that you want to include in the image.
2	Load the custom image using the Vanguard Software Loader.

Viewing Alarms and Reports

Alarms and Reports appear in the CTP or in your network management system. For explanations of Vanguard alarms and fatal error reports (FERs), see the *Vanguard Alarms and Reports Manual* (Part Number T0005), or visit the Alarms Search database on: www.vanguardms.com/support/

Service Pak 6.5P03A Change Requests and Software Improvements

Overview

The table below lists change requests and software improvements. Change requests reported to Customer Service have an assigned change request number, and, in most cases, interim patches are released to fix the problems. These change requests and software improvements are incorporated into the Vanguard Applications Ware Release V65P03A, and, where applicable, interim patch releases have been replaced by the Release V65P03A:

■ Note

The Change Request Number and Limitation Number are numbers assigned by Vanguard Managed Solutions and are used exclusively for tracking purposes.

<i>Change Request Number</i>	<i>Limitation Number</i>	<i>Release Where Problem was Reported</i>	<i>Interim Patch Release Replaced by 6.5P03A Point Release</i>	<i>Problem or Enhancement Description</i>
15951	N/A	6.5R000	6.4T1TB	Vanguard Quad FXO Busy Tone Disconnect Time Between 2-10 Sec.
N/A	N/A	6.5R000	N/A	Vanguard 7300 & 64XX Support for Brazilian R2 MFC-5C Voice Signaling Protocol
15597	N/A	6.4R00A	6.4T1ZA	Fax Incompatibility between DSP Option 1 & Option 2
15681	N/A	6.4R00A	6.4T1TA	V.90 Modem connectivity issue with CTS

■ Note

For more information on these new features refer to the Vanguard Voice Manual (Part Number T0104-05).