

VANGUARD 34x SERIES HARDWARE ADVISORY NOTICE

Introduction

This notice describes a hardware change on the Vanguard 34x Series.

Vanguard 32 MB SDRAM DIMM Part Numbers

This Hardware Advisory Notice (HAN) applies only to the Vanguard 32 MB SDRAM DIMM with model PC-68357. This HAN accompanies only this Vanguard 32 MB SDRAM DIMM when it is shipped separately.

Using the Vanguard 32 MB SDRAM DIMM

If the 32 MB SDRAM DIMM is going to be installed in a Vanguard 342 or Vanguard 340 Enhanced, you may need to download a new Vanguard Boot Prom first. If the SDRAM DIMM is identified with the words “VIKING COMPONENTS” in silk screen on the PCB and a label with the part number “VI8GU083236BTB”, then the Boot Prom installed in your Vanguard 342 or 340 Enhanced must be version 2.31 or later. To install a new Boot Prom, go to the Vanguard Managed Solutions web site and locate the Vanguard Boot Proms page under Software and Tools.

http://www.vanguardms.com/support/software_and_tools/

Locate the required Boot Prom for your platform, Vanguard 342 or 340 Enhanced and click on the image or file name to download it. Load the Boot Prom image into the product. Reference the “Vanguard Applications Ware Software Installation and Coldloading Manual” (Part Number T0028) on:

<http://www.vanguardms.com/support/documentation>

The boot code can also be loaded using the Release 6.4 Vanguide CD.



T0269 A