

**Vanguard 7300 Series
CPV8540B Carrier Card
Hardware Advisory Notice**

**What's in this
Notice**

If a 64-Bit Carrier Card (PC 1112-10028) is to be installed in a 7300 series chassis that contains a new Processor Card, any Serial Cards in the chassis may have to be upgraded first.

**Configuration
Constraints for
CPV8540B
Carrier Card**

If you install a 64-Bit Carrier Card (PC/Assembly 1112-10028/62924-02) and have a New 7300 Processor Card (PC/Assembly 1112-10011/76361G01), all Serial Cards (PC/Assembly 53130/62922-xx) in the chassis must be part number 62922-02.

The 64-Bit Carrier Card can be identified by the part number on the front rail (CPV8540B).

The Serial Card can be identified by the yellow partnumber label on the card.

The old CPU card (PC 53120) can be identified by 2 – USB ports on the front rail. The new CPU Card (PC 1112-10011) does not have USB ports on the front rail.

Actions to take: Please call Customer Service Logistics at 800-544-0062 Option #3 to arrange for an RMA to have your Serial Card upgraded prior to installing the 64-Bit Carrier Card (PC 1112-10028). Upgrade fee may apply.



T0276 B