

**Vanguard 7300 Series
Installation Manual
Hardware Advisory Notice**

**What's in This
Notice**

This notice corrects an error in the Vanguard 7300 Series Installation Manual concerning the 7310 and 7330 Version 2 DC power terminal block contact identification.

**Power Supply
Input Contacts**

Figure B-3 on page B-13 of the Vanguard 7300 Series Installation Manual incorrectly shows the 7310 and 7330 Version 2 DC power terminal block contacts identified as follows (reading left to right as viewed from the rear of the chassis):

-48V -48V RTN GND

The correct identification of the contacts is as follows (reading left to right as viewed from the rear of the chassis):

-48V RTN -48V GND

The contacts are identified correctly on the chassis themselves.



T0277 A