

## VANGUARD V340 HARDWARE ADVISORY NOTICE Release 5.6

---

<b>Introduction</b>	This notice describes hardware improvements made to the Vanguard 340 product.
<b>Software Support</b>	This version of the Vanguard 340 product is supported by Release 5.6 and greater of the Vanguard Managed Solutions Applications Ware software. Applications Ware Release 5.6 is fully compatible with the previous version of the Vanguard 340 product.
<b>Enclosure</b>	To improve ventilation and reliability of the product, this version of the Vanguard 340 has additional cooling vents on the top of the enclosure.
<b>Rear Panel</b>	The rear panel of the Vanguard 340 has two openings that accommodate Vanguard Daughtercards. Previously, if daughtercards were not installed, these openings would be covered by a panel held in place with two screws. This version of the Vanguard 340 provides a “knockout” plate for the two openings in the rear panel. For availability, consult your Vanguard Managed Solutions Sales representative.
<b>How to Distinguish the New Version from the Old</b>	The rating label on the bottom of the unit is marked “Vanguard 340 Version 2”. The Motherboard assembly level Part Number is 75101G10.

---



T0178-03 A

## VANGUARD V340 HARDWARE ADVISORY NOTICE Release 5.6

---

<b>Introduction</b>	This notice describes hardware improvements made to the Vanguard 340 product.
<b>Software Support</b>	This version of the Vanguard 340 product is supported by Release 5.6 and greater of the Vanguard Managed Solutions Applications Ware software. Applications Ware Release 5.6 is fully compatible with the previous version of the Vanguard 340 product.
<b>Enclosure</b>	To improve ventilation and reliability of the product, this version of the Vanguard 340 has additional cooling vents on the top of the enclosure.
<b>Rear Panel</b>	The rear panel of the Vanguard 340 has two openings that accommodate Vanguard Daughtercards. Previously, if daughtercards were not installed, these openings would be covered by a panel held in place with two screws. This version of the Vanguard 340 provides a “knockout” plate for the two openings in the rear panel. For availability, consult your Vanguard Managed Solutions Sales representative.
<b>How to Distinguish the New Version from the Old</b>	The rating label on the bottom of the unit is marked “Vanguard 340 Version 2”. The Motherboard assembly level Part Number is 75101G10.

---



T0178-03 A