

## VANGUARD 7300 SERIES HARDWARE ADVISORY NOTICE Release 6.1.T14A

---

### Introduction

This notice describes a hardware change on the Vanguard 7300 series system card.

---


### Vanguard 7300 CPU Card Upgrade

The Vanguard 7300 Series MCP750 (part number 75836G02) system cards are supported by software releases 6.1.T14A and greater. If you have a part number 75836G02 system card and are running older versions of release 6.1, a new 6.1 software patch is required (6.1.T14A). The system cards have a different revision PCI-PCI bridge than previous system cards (part number 75836G01). The new system cards are not being recognized by software older than 6.1.T14A. Software patch 6.1.T14A must be installed when using part number 75836G02.

---

### Checking the Part Number Label

Figure 1 shows the revision label, located on the side of the unit.



**Figure 1. Part Number Label**

---

### Software Patch 6.1.T14A

The default images and executable patch are available at:

[http://www.vanguardms.com/support/software\\_and\\_tools/vanguard/special\\_releases/](http://www.vanguardms.com/support/software_and_tools/vanguard/special_releases/)

